




Venus 6 USB GPS Firmware Update

For performing a firmware update of the Venus 6 based CTFGPS-3 USB GPS receiver, you need the program SkyTraQ 0.4.213 BlueTooth and the firmware file (egl: STI_01.03.25-01.06.22_2x_agps_log_4800.bin).

Start SkyTraQ 0.4.213 BlueTooth and click on the folder symbol which you can see on the picture below.






CARTFT.COM
Shop for mobile
PC- and GPS-Solutions

Power Up Your Car

Choose the firmware file and click on „Open“.






CARTFT.COM
Shop for mobile
PC- and GPS-Solutions

Power Up Your Car

Click on the red marked button to perform the update. This process can take some minutes. Do not disconnect the receiver while updating ! This can lead to damages !



After the update is finished you can perform a functionality test with the SkyTraq program.

Set the right COM Port, choose baudrate 4800 and click on „Connect“.

-- Timo Decristan (Fluxkompensator)